

#### Electromechanical Energy Conversion – I

Ву

Prof. Dr. A. Mete VURAL mvural@gantep.edu.tr

#### References

• Electric Machinery Fundamentals, Stephen Chapman, 4th Edition, McGraw-Hill

#### (Course Book)

• Electric Machinery, A.E. Fitzgerald, Charles Kingsley, JR., Stephen D. Umans, 6th Edition, McGraw-Hill

#### (Supplementary Book)



1



#### Contents

Chapter 1 – Introduction to Machinery Principles (Chapter 1 in course book)

Chapter 2 – Transformers (Chapter 2 in course book)

Chapter 3 – DC Machinery Fundamentals (Chapter 8 in course book)

Chapter 4 – DC Motors and Generators (Chapter 9 in course book)

# **Grading Policy**

- Midterm-1 : 20%
- Midterm-2 : 20%
- Lab : **20%**
- Final : **40%**
- TOTAL : 100%
- ✓ Exams are closed-book

✓ Homework(s)/Project can be assigned during the semester

(The performances of the students will be included into the grading policy)

- ✓ Attendance is minimum 70% to class
- ✓ Attendance is minimum 80% to laboratory works

4

6

SDVICE



Students who has registered to EEE 321 **MUST follow** the <u>web</u> <u>page of Dr. A. Mete VURAL</u> for all announcements and getting other course related materials.

http://eee.gantep.edu.tr/pages.php?url=akademik-personel-2

#### Some Advices !

- Keep attendance as much as poosible ! (70% or more)
- Take your own notes
- Practice is good. Do it as much as possible
- Do not try to summarize, try to learn the fundamental idea
- Solve examples, problems as many as possible
- Make your study plan by yourself
- Know yourself ! Study alone or within a group
- Do not postpone anything ! Do it now







		The Prefixes Used with SI Units	
Prefix	Symb	ol Meaning	Scientific Notation
exa-	E	1,000,000,000,000,000	10 <sup>18</sup> 10 <sup>15</sup>
tera-	T	1,000,000,000,000	1012
giga-	G	1,000,000,000	10 <sup>9</sup>
mega-	M	1,000,000	10 <sup>6</sup>
kilo-	k	1,000	10 <sup>3</sup>
hecto-	h	100	10 <sup>2</sup>
deka-	da	10	101
-	_	1	10 <sup>0</sup>
deci-	d	0.1	10-1
centi-	с	0.01	10-2
milli-	m	0.001	10-3
micro-	μ	0.000 001	10-6
nano-	n	0.000 000 001	10-9
pico-	р	0.000 000 000 001	10-12
femto-	f	0.000 000 000 000 001	10-15
atto-	а	0.000 000 000 000 000 001	1 10-18







# CHAPTER 1 INTRODUCTION TO MACHINERY PRINCIPLES





# Why are motors/generators/transformers are frequently used in modern daily life ?



# Why are motors/generators/transformers are frequently used in modern daily life ?

#### The answer is simple:

Electrical power is a **clean** and **efficient energy source** that is easy to transmit over long distances, and easy to control.







# Why are motors/generators/transformers are frequently used in modern daily life ?

• An electric motor has higher efficiency when compared to internal-combustion engine.



• An electric motor **does not need strong constant ventilation** (air/water) when compared to internal-combustion engine.









#### Angular acceleration

- Angular acceleration ( $\alpha$ ) is the rate of change in angular velocity with respect to time.
- It is assumed **positive** if the angular velocity is **increasing** in an algebraic sense.
- Angular acceleration is the rotational analog of the concept of acceleration on a line.
- The unit of angular acceleration is rad/s<sup>2</sup>

$$\alpha = \frac{dw}{dt}$$

## Torque

- In linear motion, a force applied to an object causes its velocity to change. In the absence of a net force on the object, its velocity is constant or the object is stationary.
- The greater the force applied to the object, the more rapidly its velocity changes.
- There exists a similar concept for rotational motion: When an object is rotating, its angular velocity is constant unless a torque is present on it.
- The greater the torque on the object, the more rapidly the angular velocity of the object changes.

#### Torque

- In figure (a), a force applied to a cylinder so that it passes through the axis of rotation, so torque is zero.
- In figure (b), a force applied to a cylinder so that its line of action misses the axis of rotation. Here torque is <u>not</u> <u>zero</u> and it is in counterclockwise (CCW) direction.



## Torque

- The torque on an object is defined as the product of the force applied on the object and the perpendicular distance between the line of the applied force and the center of rotation.
- Torque is generally represented by the symbol "au"
- The unit of torque is (Newton) x (meter) → Nm



#### Torque Typical Torque-speed curve of a DC motor (shown at right) Torque-Speed for Maxon Geared Output 0.35 0.3 0.25 (백) (파란) 0.15 0.1 0.05 300 RPM 200 400 50 Source: http://lancet.mit.edu/motors/motors1.html Source: http://lancet.mit.edu/motors/motors3.html 28

#### Newton's law of rotation

Newton's law for objects moving <u>along a straight line</u> describes the relationship between the force applied to an
object and its resulting acceleration. This relationship is given by the equation:

F = ma

where, F is the net force applied to an object (N) m is the mass of the object (kg) a is the resulting acceleration of the object  $(m/s^2)$ 

• The similar idea can be thought for the rotating objects:

 $\tau = J\alpha$ 

where,  $\tau$  is the net torque applied to an object (Nm) *J* is the "**moment of inertia**" of the object (kg.m<sup>2</sup>)  $\alpha$  is the resulting angular acceleration of the object (rad/s<sup>2</sup>)

**Moment of inertia:** A quantity expressing a body's tendency to resist angular acceleration

29

#### Newton's law of rotation Motor data Pole number 2p Torque constant (100 K) 0.835 Nm/A **k**T Voltage constant (at 20 °C) Winding resistance (at 20 °C) ke R<sub>ph</sub> V/1000 rpm 53.0 0.815 Ω LD Tel Tmech Rotating field inductance mΗ 10.2 Electrical time constant ms 12.5 Mechanical time constant 0.44 ms Thermal time constant Tth min 45 kgm<sup>2</sup> 0.126.10-3 Moment of inertia JMot Nm/rad Shaft torsional stiffness 9800 G Weight without brake 7.4 kg Source: https://electronics.stackexchange.com Parameter Value Armature resistance 8.91 Ω $R_a$ Armature inductivity $L_a$ 4.5 mH Moment of inertia $J_e$ $(2.93e-5 \text{ kg m}^2)$ Coefficient of viscous friction $F_{e}$ 11.7e-5 kg m<sup>2</sup>/rad/s Electromechanical constant k<sub>em</sub> 0.103 Nm/A 0.103 V/rad/s Mechanical-electrical constant kme Tacho constant $k_{tg}$ 0.0191 V/rad/s Source: https://www.researchgate.net/publication/268654073\_Fuzzy\_Model\_Reference\_Adaptive\_Control\_of\_Velocity\_Servo\_System/figures?lo=1 30

#### Work

• For linear motion, work is defined as the application of a force through a distance:

$$W = \int F. dr$$

• If Force is constant;

$$W = Fr$$

- The unit of work is **Joules (J)**
- For <u>rotational motion</u>, work is the application of a torque through an angle:

$$W = \int \tau . d\theta$$

• If Torque is constant;

 $W = \tau \theta$ 

#### Power

• Power is the rate of doing work, or the increase in work per unit time. The equation for power is

$$P = \frac{dW}{dt}$$

• It is usually measured in joules per second or Watts (W), but also can be measured in horsepower (hp):

1 hp = 746 Watts (W)Example: Calculate the torque on the shaft of a DC  
motor if shaft speed is 600 rpm and the motor's  
output power under this condition is 10 hp.• If Force is constant in linear motion:Solution:  
$$P = \frac{dW}{dt} = \frac{d}{dt}(Fr) = F\frac{dr}{dt} = F.v$$
  
• If Forque is constant in rotational motion:Solution:  
 $P = 10hp = 10x746W = 7460W$   
 $w = \frac{2\pi n}{60} = \frac{2\pi (600)}{60} = 62.83 rad/s$   
 $\tau = \frac{P}{w} = \frac{7460W}{62.83 rad/s} = 118.73Nm$ 



#### The Magnetic Field

- Magnetic fields are the fundamental mechanism by which energy is converted from one form to another in motors, generators, and transformers.
- Four basic principles describe how magnetic fields are used in these devices:
- 1) A current-carrying wire produces a magnetic field in the area around it. (Ampere's Law)



Ampere's Law states that for any closed loop path, the sum of the length elements times the magnetic field in the direction of the length element is equal to the permeability times the electric current enclosed in the loop.





• Solve the Example 1-6 at page 31 from Chapman



• Solve the Example 1-7 at page 33 from Chapman



- Solve the Example 1-8 at page 34 from Chapman
- Solve the Example 1-9 at page 34 from Chapman





#### Production of a Magnetic Field

- The magnetic field intensity H is defined as the effort exerted by the current to establish a magnetic field.
- The relationship between the <u>magnetic field intensity H</u> and the resulting <u>magnetic flux density B</u> produced within a material is given by

 $B = \mu H$ 

where H is the magnetic field intensity (A-turn/m)  $\mu$  is the permeability of material (core) (H/m) B is the resulting magnetic flux density (Tesla (T) or Wb/m<sup>2</sup>)

#### Production of a Magnetic Field

• Permeability  $\mu$  represents the relative ease of establishing a magnetic field in a given material.

 $B = \mu H$ 

- So the greater permeability, the greater amount of B established for an existing H.
- The permeability of free space (air) is constant:

 $\mu_0 = 4\pi x 10^{-7}$  (H/m)

• The permeability of any other material in nature compared to the permeability of free space is called **«relative permeability»** of that material:

$$\mu_r = \frac{\mu}{\mu_0}$$

• Although  $\mu_0$  is constant, the permeability of the materials in nature is **not constant** !

44



#### Production of a Magnetic Field

• If we linearize (approximate) the **B-H curve** of the material for a given region or operating range),  $\mu_r$  can be thought as <u>constant</u> !

Material	<b>Relative Permeability</b>		
Copper	0.9999906		
Silver	0.9999736		
Lead	0.9999831		
Air	1.0000037		
Oxygen	1.000002		
Aluminum	1.000021		
Titanium 6-4 (Grade 5)	1.00005		
Palladium	1.0008		
Platinum	1.0003		
Manganese	1.001		
Cobalt	250		
Nickel	600		
Iron	280,000		

- Diamagnetic material (repelled by a magnetic field)
  - Non-magnetic material (they are not magnetized)
  - **Paramagnetic material (**they become magnetized in a magnetic field but their magnetism disappears when the field is removed)
  - **Ferromagnetic materials (**attracted by a magnetic field and they can retain their magnetic properties even the magnetic field is removed**)**

#### Production of a Magnetic Field Relative permeability values for important types of ferromagnetic materials Material Max. µr value Silicon-iron 7000 Cobalt-iron 10 000 Permalloy 45 23 000 Permalloy 65 600 000 Silicon Steel Transformer Lamination Mumetal 100 000 Source: https://www.indiamart.com Supermalloy 1 000 000 Typical dust core 10-100 Ferrite core 100-2000 Source: http://machineryequipmentonline.com **Transformer Ferrite Core** Source: https://uk.rs-online.com 47





#### **Magnetic Circuits**

- In an electrical circuit, a voltage or electromotive force (EMF) produces current in the circuit (Figure (a)).
- On the other hand, the current in a coil of wire wrapped around a core produces a magnetic flux (Ø) in the core. (Refer to the previous slide)
- Hence these two events can be considered to be analogous so that we can begin to think about magnetic circuits.
   In a magnetic circuit, the magnetomotive force (MMF) produces flux in the circuit (*Figure (b)*).



#### **Magnetic Circuits**

- Magnetic circuits do not exist in real-life.
- They are often used to model the magnetic behavior of electrical machines with **up to the 5% of error**.
- By this way, the analyzing/design stages are simplified.
- Like the voltage source in the electrical circuit, the MMF in the magnetic circuit has a polarity associated with it.
- The **positive end** of the MMF source is the end from which the flux <u>exits</u>.
- The negative end of the MMF source is the end at which the flux <u>reenters</u>.

The **polarity of the MMF** can be determined from the modification of the <u>right-hand rule</u>:

If the fingers of the right hand curl in the direction of the current in the coil, then the thumb will point in the direction of the positive MMF.



#### Production of a Magnetic Field

- The permeance (P) of a magnetic circuit is defined as the reciprocal of its reluctance:
- The permeance is analogous to the conductance in an electrical circuit.

$$P = \frac{1}{\mathcal{R}}$$

where P is the permeance **(Wb/Ampere-turns)**  $\mathcal{R}$  is the reluctance **(Ampere-turns/Wb)** 

Since;

$$\phi = \frac{\mathcal{F}}{\mathcal{R}} \quad \Longrightarrow \quad \phi = P.\mathcal{F}$$

# Production of a Magnetic Field

• So far we know that **reluctance** is the ratio of MMF to flux in a magnetic circuit:

$$\phi = \frac{\mathcal{F}}{\mathcal{R}} \quad \Longrightarrow \quad \mathcal{R} = \frac{\mathcal{F}}{\phi}$$

• Alternatively, can we calculate the reluctance with physical parameters of the magnetic circuit

 $\phi = \frac{\mathcal{F}\mu A}{l_c} = \frac{\mathcal{F}}{\mathcal{R}} \implies \mathcal{R} = \frac{l_c}{\mu A} \quad (H^{-1})$ 

Since;

$$\phi = \frac{\mu N. i. A}{l_c}$$
 (previously derived on slide 44)

• and;

 $\mathcal{F}=N.\,i$ 



Comparison of magnetic circuit and electrical circuit parameters

Magnetic circuit	Electrical circuit
Magnetomotive force (MMF)	Electromotive force (EMF)
Flux	Current
Reluctance	Resistance
Permeance	Conductance

54





- Why are the calculations in a magnetic circuit approximate ? (Accuracy is up to 5%)
- There are **four** reasons:

**1)** The magnetic circuit concept assumes that all the flux is confined within a magnetic core. Unfortunately, this is not quite true. Because the permeability of a ferromagnetic core is too much higher than that of air and a small fraction of the flux escapes from the core into the surrounding low-permeability air. This flux outside the core is called **leakage flux**, and it plays a very important role in electric machine design.





#### Production of a Magnetic Field

- Why are the calculations in a magnetic circuit approximate ? (Accuracy is up to 5%)
- There are **four** reasons:

**3)** In ferromagnetic materials, the permeability <u>varies</u> with the amount of flux already in the material. This nonlinear effect has been previously discussed in the slides. Because of this nonlinearity, in practice, the reluctance values are <u>not constant</u>.





#### Production of a Magnetic Field

**Example-1:** The magnetic circuit shown in Fig. 1.2 has dimensions  $Ac = Ag = 9 \text{ cm}^2$  (*fringing effect is neglected*), g = 0.050 cm, Ic = 30 cm, and N = 500 turns. Assume the value  $\mu_r = 70,000$  for the core material.

(a) Find the reluctances of the core and the air gap.

(b) Find the flux and the current for the condition that the magnetic circuit is operating with a magnetic flux density of **1.0 T**.



Figure 1.2 Magnetic circuit with air gap.



- Repeat the previous example for a fringing effect of 5%
- Solve the following examples from Chapman
  - Example 1-1 at page 14
  - Example 1-2 at page 17
  - Example 1-3 at page 19









#### Magnetic Behavior of Ferromagnetic Materials

- The advantage of using a ferromagnetic material for cores in electrical machines and transformers is that one gets many times **more flux** for a given magnetomotive force with ferromagnetic material than with air.
- However, if the resulting flux has to be **proportional**, or nearly so, to the applied magnetomotive force, then the core must be operated in the **unsaturated region** of the magnetization curve.
- Since real generators and motors depend on magnetic flux to produce voltage and torque, they are designed to produce **as much flux as possible**.
- As a result, most real machines **operate near the knee of the magnetization curve**, and the flux in their cores is **not linearly related** to the magnetomotive force producing it.
- This nonlinearity brings design and analysis difficulties for the electrical machines.





#### Example for inductance calculation

The magnetic circuit shown below consists of an **N-turn** winding on a magnetic core of **infinite permeability** with two parallel air gaps of lengths **g1** and **g2** and areas **A1** and **A2**, respectively.

Find the inductance of the winding (Neglect fringing effects at the air gaps).





#### Solution

a. The equivalent circuit of Fig. 1.6b shows that the total reluctance is equal to the parallel combination of the two gap reluctances. Thus

$$\phi = \frac{Ni}{\frac{\mathcal{R}_1 \mathcal{R}_2}{\mathcal{R}_1 + \mathcal{R}_2}}$$

where

$$\mathcal{R}_1 = \frac{g_1}{\mu_0 A_1} \qquad \qquad \mathcal{R}_2 = \frac{g_2}{\mu_0 A_2}$$

Reluctances of the air gaps

From Eq. 1.29,

$$L = \frac{\lambda}{i} = \frac{N\phi}{i} = \frac{N^2(\mathcal{R}_1 + \mathcal{R}_2)}{\mathcal{R}_1 \mathcal{R}_2}$$
$$= \mu_0 N^2 \left(\frac{A_1}{g_1} + \frac{A_2}{g_2}\right) \quad \text{Inductance of the winding}$$

#### Self-study

- Solve the following examples from Chapman
  - Example 1-4 at page 24
  - Example 1-5 at page 25

#### Self-Inductance and Mutual Inductance

The total MMF of the magnetic circuit as shown:

$$\mathcal{F} = N_1 i_1 + N_2 i_2$$

If the core reluctance is neglected ( $\mu_{core} \rightarrow \infty$ ) and assuming that there is no fringing effect:

$$\phi = (N_1 i_1 + N_2 i_2) \frac{\mu_0 A_c}{g}$$

The flux linkage of coil 1 is

$$\lambda_{1} = N_{1}\phi = N_{1}^{2} \left(\frac{\mu_{0}A_{c}}{g}\right) i_{1} + N_{1}N_{2} \left(\frac{\mu_{0}A_{c}}{g}\right) i_{2}$$

$$L_{11}$$

$$L_{12}$$





$$\begin{split} \lambda_1 &= L_{11}i_1 + L_{12}i_2\\ L_{11} \text{ is called } & \overset{\text{self-inductance}}{=} \text{ of coil 1}\\ L_{12} \text{ is called } & \overset{\text{mutual inductance}}{=} \text{ between coils 1 and 2}\\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & & \\ & & & & & & \\ & & & & & & \\ & & & & & & \\ & & & & & & \\ & & & & & & \\ & & & & & & \\ & & & & & & \\ & & & & & & \\ & & & & & & \\ & & & & & & \\ & & & & & & & \\ & & & & & & & \\ & & & & & & & \\ & & & & & & & \\ & & & & & & & \\ & & & & & & & \\ & & & & & & & \\ & & & & & & & \\ & & & & & & & \\ & & & & & & & \\ & & & & & & & \\ & & & & & & & \\ & & & & & & & \\ & & & & & & & \\$$

#### Self-Inductance and Mutual Inductance

Similarly, the flux linkage of coil 2 is

$$\lambda_{2} = N_{2}\phi = N_{1}N_{2}\left(\frac{\mu_{0}A_{c}}{g}\right)i_{1} + N_{2}^{2}\left(\frac{\mu_{0}A_{c}}{g}\right)i_{2}$$

It is important to see that;

$$L_{21} = L_{12} = N_1 N_2 \left( \frac{\mu_0 A_c}{g} \right)$$

 $\lambda_2 = L_{21}i_1 + L_{22}i_2$  $L_{22}$  is called «self-inductance of coil 2

 $L_{21}$  is called «<u>mutual inductance</u>» between coils 2 and 1

#### Faraday's Law and Inductance

Faraday's Law states that

$$e = \frac{d\lambda}{dt}$$

And the definition of flux linkage is

 $L = \frac{\lambda}{i}$ 

Combining these two equations yields

$$e = \frac{d\lambda}{dt} = \frac{d(L,i)}{dt} = L\frac{di}{dt} + i\frac{dL}{dt}$$

For static magnetic circuits (no rotation) L becomes constant. So;

$$e = L \frac{di}{dt}$$

 For rotating magnetic circuits, such as in electrical machines, L is <u>not constant</u> and <u>time-varying</u>. So;

$$e = L\frac{di}{dt} + i\frac{dL}{dt}$$

**quantity** because of continuous change of the relative positions of the stator and rotor windings due to the rotation of the rotor.

In electrical machines *L* is a *time-varying* 

75

#### Power and Energy in Magnetic Circuits

The power at the terminals of a winding on a magnetic circuit is a measure of the rate of energy flow into the circuit through that particular winding. The **power**, **p**, is determined from the product of the voltage and the current

$$p = ie = i \frac{d\lambda}{dt}$$
 The unit of power is **Watts (W)**

Thus the change in magnetic stored energy  $\Delta W$  in the magnetic circuit in the time interval  $t_1$  to  $t_2$ 

$$\Delta W = \int_{t_1}^{t_2} p \ dt = \int_{\lambda_1}^{\lambda_2} i \ d\lambda$$
 The unit of energy is **Joules (J)**

$$\Delta W = \int_{\lambda_1}^{\lambda_2} i \, d\lambda = \int_{\lambda_1}^{\lambda_2} \frac{\lambda}{L} \, d\lambda = \frac{1}{2L} \left( \lambda_2^2 - \lambda_1^2 \right) \quad \Longrightarrow \quad$$

If we assume  $\lambda_1 = 0$  at  $t = t_1$ 

 $W = \frac{1}{2L}\lambda^2 = \frac{L}{2}i^2$  The total magnetic stored energy at any given value of  $\lambda$ 

#### Self Study

For the magnetic circuit shown below, find

(a) the inductance L

- (b) the magnetic stored energy for a core flux density of B = 1.0 T
- (c) the induced voltage for a 60-Hz time-varying core flux density of B = 1.0 sin(wt) T where w =  $(2.\pi.f)$ , f=60 Hz.

















## AC Excitation and Hysteresis Loop

- When an external magnetic field is applied to the ferromagnetic material, the magnetic fields of all domains are lined up in the direction of the applied field.
- Since all domains are lined up in the same direction, a magnetic field in the ferromagnetic material is generated like a magnet.
- □ This generated magnetic field and the externally applied magnetic field support each other and they are added together.
- Because of this addition, a ferromagnetic material has much bigger amount of magnetic field when compared with air under the same amount of H.
- $\Box$  As a result, a ferromagnetic material has a much higher permeability than air. (for example  $\mu = 7000\mu_0$ )





#### Hysteresis Loss

- **Turning and reorientation** the domains during each cycle of the alternating current in the ferromagnetic material requires some energy.
- This energy requirement is known as «hysteresis loss» in the ferromagnetic materials.
- Hysteresis loss causes heating in the core (ferromagnetic) materials.
- Hysteresis loss occurs in all electrical machines and transformers.
- The area of the hysteresis loop is directly proportional to the hysteresis loss.
- The smaller the applied current or MMF, the smaller the area of the resulting hysteresis loop.









#### **Eddy Current Loss**

- A time-changing flux induces voltage within a ferromagnetic core (Faraday's Law).
- This is just the same manner as it would be in a wire wrapped around that core.
- These voltages cause swirls of current to flow within the core.
- Since these eddy currents flow in the core, the core becomes warm and some energy is dissipated by the core.

The equation for *eddy current loss* is given as:

 $P_e = K_e.B_{max}^2.f^2.th^2.V$ 

where  $P_e$  is the eddy current loss (Watt)  $K_e$  is the eddy current constant  $B_{max}$  is the peak value of magnetic flux density (Wb/m<sup>2</sup>) f is the frequency (Hz) th is the material thickness (m) V is the volume (m<sup>3</sup>)

**Eddy Current Loss** 

- As observed from the eddy current loss equation, the amount of energy lost is proportional to the square of the thickness and the volume of the material.
- · For this reason, it is customary to break up the ferromagnetic core into many small laminations.
- An insulating oxide or resin is used between these laminations.
- Because the insulating layers are extremely thin, this action reduces eddy current losses without changing too much the magnetic properties of the core.



Eddy currents in laminated cores (*right*) are smaller than those in solid cores (*left*)

Source: https://www.motioncontroltips.com/hysteresis-loss/

#### Self Study

The magnetic core shown in Figure is made from laminations of M-5 grain-oriented electrical steel. The winding is excited with a 60-Hz voltage to produce a flux density in the steel of B = 1.5 sin wt T, where w =  $2\pi$ 60 rad/s. The steel occupies 94% of the core cross sectional area. The density of the steel is 7.65 g/cm<sup>3</sup>.

Find

- (a) the applied voltage,
- (b) the peak current,
- (c) the rms exciting current,
- (d) the core loss.





#### Permanent Magnets

- Permanent magnets have a large residual flux.
- Residual flux means that without excitation (no current is applied), the magnet produces a high flux by itself.
- Permanent magnets also have a large coercive MMF.
- Coercive MMF is the MMF that is required to make the flux in the permanent magnet zero.
- **Coercivity** can be thought of as a measure of the magnitude of the MMF required to **demagnetize** the material.
- Permanent magnets find application in many devices, including loudspeakers, ac and dc motors, microphones, and analog electric meters.



#### Permanent magnet example:

As shown in the Figure, a magnetic circuit consists of a core having **infinite permeability**, an air gap of length g = 0.2 cm, and a section of magnetic material of length Im = 1.0 cm. The cross-sectional area of the core and gap is equal to Am = Ag = 4 cm<sup>2</sup>.

Calculate the flux density B in the air gap if the magnetic material is (a) M-5 electrical steel (b) Alnico 5



Permanent magnet example:  $\mu \rightarrow \infty$ Solution: Area Magnetic Am material 1 Since the core permeability is assumed infinite, H in the core is negligible. ţg 1<sub>m</sub> Air gap, permeability  $\omega = \frac{B}{H}$  $\mu_0$ , Area  $A_p$  $\mu \rightarrow \infty$ Since the MMF acting on the magnetic circuit is zero (No windings), we can write:  $\mathcal{F} = 0 = H_{g}g + H_{m}l_{m}$ or  $H_g = -\left(\frac{l_m}{g}\right) H_m \qquad \longrightarrow \qquad H_g = -\frac{1}{0.2} H_m \qquad \longrightarrow \qquad H_g = -5H_m$ 98







#### The Largest B-H Product of Permanent Magnet

- A useful measure of the capability of permanent magnets is known as «maximum energy product».
- This corresponds to the largest B-H product which corresponds to a point on the second quadrant of the hysteresis loop as shown in the figure.
- The permanent-magnet at this point will result in the <u>smallest volume</u> of that material required to produce a given flux density in an air gap.
- •
- So, choosing a material with the largest available maximum energy product can result in the smallest required magnet volume.



## Self Study

The magnetic circuit of the following figure has an air-gap area of  $Ag = 2.0 \text{ cm}^2$ . Find the minimum magnet volume required to achieve an air-gap flux density of 0.8 T.



#### Self-study

- Review and read Section 1.9 "Real, Reactive, and Apparent Power in AC Circuits"
- Solve all problems of Chapter 1 from Chapman

#### **Review Questions**

- 1) What is torque? What role does torque play in the rotational motion of machines?
- 2) What is Ampere's law?
- 3) What is magnetizing intensity? What is magnetic flux density? How are they related?
- 4) How does the magnetic circuit concept aid in the design of transformer and machine cores?
- 5) What is reluctance?
- 6) What is a ferromagnetic material? Why is the permeability of ferromagnetic materials so high?
- 7) How does the relative permeability of a ferromagnetic material vary with magnetomotive force?
- 8) What is hysteresis? Explain hysteresis in terms of magnetic domain theory.
- 9) What are eddy current losses? What can be done to minimize eddy current losses in a core?
- 10) What is Faraday's law?
- 11) What conditions are necessary for a magnetic field to produce a force on a wire?
- 12) What conditions are necessary for a magnetic field to produce a voltage in a wire?
- 13) Will current be leading or lagging voltage in an inductive load? Will the reactive power of the load be positive or negative?
- 14) What are real, reactive, and apparent power? What units are they measured in? How are they related?
- 15) What is power factor?

#### **END OF CHAPTER 1**

**INTRODUCTION TO MACHINERY PRINCIPLES**